

From: [Scott Jones](#)
To: [Miller, Garyg](#)
Cc: [Walters, Donn](#); [Sanchez, Carlos](#)
Subject: Got it and question for you... RE: SJRWP December 2015 Sample Results
Date: Wednesday, February 24, 2016 11:47:10 AM
Attachments: [removed.txt](#)
[image002.png](#)
[image003.png](#)
[image004.png](#)

Thanks, Gary. I will try to get these items posted by next week.

While I have you...

I jotted down in my notes from the public meeting that the December EPA dive team inspection that ended up finding the gap in the NW corner was the result of concerns about last year's flood/high water events. Was community concern the reason for the inspection, or was it a regularly scheduled inspection? If it was the former, was it because of SJRC/Jackie Young's request or was it from some other entity?

Scott

Scott A. Jones
Director of Advocacy

sjones@galvbay.org

Phone: 281-332-3381 x 209 | Fax: 281-332-3153

www.galvbay.org

17330 Hwy. 3, Webster, TX 77598



Protecting the natural resources of Galveston Bay since 1987

From: Miller, Garyg [mailto:Miller.Garyg@epa.gov]
Sent: Tuesday, February 23, 2016 1:47 PM
To: sjones@galvbay.org
Cc: Walters, Donn; Sanchez, Carlos
Subject: SJRWP December 2015 Sample Results

Scott,

Here are the sediment sample results from the December 2015 sediment sampling at the San Jacinto site. The first file is the lab report from the samples collected/analyzed by the EPA contractor; and the second file are results tables for the Potentially Responsible Parties' samples. The last file is a map showing where the samples were collected.



9746042

Regards,

Gary Miller

Remedial Project Manager

EPA Region 6 – Superfund Division (6SF-RA)

214-665-8318

miller.garyg@epa.gov

***** ATTACHMENT REMOVED

This message contained an attachment which the administrator has caused
to be removed.

***** ATTACHMENT REMOVED

Attachment name: [image001.jpg]
Attachment type: [image/jpeg]